

APPENDIX A

DA Form 4753, Notice of Unsafe or Unhealthful Working Conditions

<p>NOTICE NO. <u>1</u> OF</p> <p>UNSAFE OR UNHEALTHFUL</p> <p>WORKING CONDITION</p> <p>(DO NOT REMOVE NOTICE UNTIL CONDITION IS ABATED)</p> <p style="font-size: small; margin-top: 20px;">For use of this form, see AR 385-10; the proponent agency is Office of The Inspector General.</p>	
1. UNIT INSTALLATION <div style="text-align: center; margin-top: 5px;">D.D.T.P.</div>	3. DATE OF INSPECTION <div style="text-align: center; margin-top: 5px;">03 SEP 1998</div>
2. OFFICIAL IN CHARGE OF WORKPLACE <div style="text-align: center; margin-top: 5px;">Mr. Johnathan Dowe</div>	4. STANDARD VIOLATED
5. LOCATION OF VIOLATION <div style="text-align: center; margin-top: 5px;">Warehouse 25 / Bay 8 / Electrical Room</div>	
6. DESCRIPTION OF UNSAFE OR UNHEALTHFUL CONDITION <div style="margin-top: 10px;"> <i>There is steam leaking from a high pressure steam line and it is encompassing the electrical control panel of freight elevator # 3.</i> </div>	
7. RECOMMENDED ABATEMENT PROCEDURES <div style="margin-top: 10px;"> a. Interim 1. Secure the elevator. 2. Open electricval room door to vent residual steam. 3. Repair or replace the appropriate steam line. </div> <hr style="border: 0; border-top: 1px solid black; margin: 10px 0;"/> <div style="margin-top: 10px;"> b. Final: Abatement should be completed by <div style="margin-top: 5px;">04 October 1998</div> </div>	
8. ADDITIONAL INFORMATION CONCERNING THIS VIOLATION CAN BE OBTAINED FROM <div style="display: flex; justify-content: space-between; align-items: flex-end; margin-top: 5px;"> <div> Mr. Frank Swartz </div> <div style="text-align: right;"> TELEPHONE NO <u>821-7356</u> </div> </div>	

